	Approved For-Release 2002/10/21: GIA-RDF / 55002	ZUU
STATINT()		
Com	MENTS ON Manage	

STATINTL PEF. MEMO.

- TESTED ARE AS PROPOSED 58/4 INCHES AS MEASURED IN THE PAST AND 5 INCHES AT THE BOTTOM WHEN PROPERLY PACKED. REGARDLESS OF HOW THICK THE CHUTES ARE THEY COMPARE WITH THE EVALUATION MOCKUP, WHICH THE DRIVERS AGREE WILL DO THE JOB FOR THEM.
- 2.) WIDTH! THIS CONDITION NO LONGER EXISTS SINCE THE PARACHUTES ARE BEING PACKED PROPERLY.
- 3.) THIS APPEARED TO BE NO PROBLEM ON THE STATIC EJECTION OF 1/22/64 IN WHICH ZERO- ZERO CAPABILITY WAS ACHIEVED. THIS WILL BE WATCHED CLOSELY ON THE STATIC EJECTION OF 1/30/64,
- 4.) WE RECOMMEND A PIECE OF WEBBING TYPE XII COND" R'BE ADDED ACROSS BOTTOM PACK FIND AT ATTACHMENT FOR REINFURCEMENT & SHAFFING.
- 5.) THIS IS BEING ACCOMPLISH FOR INFLIGHT

Approved For Release 2002/10/21 : CIA-RDP75B00200R000400020014-1

- 6) WE DO NOT FEEL THIS IS A PROBLEM.
- 1) WITH PRESENT PACKING TECHNIQUE (DE FEEL THAT THE PACK IS NO TIGHTER THAN PRESENT OPERATION PARACHUTES
- SACRIFICE FLAPS (AN BE PROVIDED TO THE CONFIGURATION OF PRESENT CHUTES, RESULTS OF PREVIOUS TEST PROGRAM SHOWED LITTLE OR NO DIFFERENCE IN RESULTS WHETHER FLAPS WERE USED OR NOT.
- 9.) THE LUNER FLAPS ARE LOOSE BUT WE FEEL
 THE ARE SERVING, THEIR INTENDED PORPOSE,
 WE CAN TIGHTENTHEM (C)THOUT COMPROMISING,
 PACKING TECHNIQUE OR FUNCTION /F THIS
 IS INSISTED OPEN.
- 10.) WE DON'T FEEL WEBBING NECESSARY HOWEVER SPACING CAN BE CHANGED TO MEET NEED OF USERS. ADDING WEBBING WILL ONLY DEFEAT THINNING THE PACK.
- 11.) THIS WILL BE COMPLIED WITH ON PRODUCTION
- 12) THE TEST PROGRAM TO DATE HAS FAILED TO SHOW THAT THIS IS A VALID POINT.

و ۱۰۰ ه

- 13.) REFERENCE / TEM 7 THIS MEMO. PACK IS

 NO THIGHTER. POUL FORCE MAY BE

 SLIGHTLY HIGHER DUE TO 4 PIN VS 3 PIN

 RIPCORD. TESTS AT STEINTHAL HAS SHOWN

 [HAT THIS RIG COILL MEET PULL REQUIREMENT

 OF MANUAL FUNCTIONS PER MIL-P. 6055

 WHICH IS 27 LB. MAX.
 - 14.) THIS WILL BE COMPLIED WITH ON OUR PRODUCTION UNITS.
 - 15.) DACKING DURING THE TEST PROGRAM TO DATE HAS NOT SHOWN THIS TO BE A PROBLEM.
 - 16.) SHEET METAL COVERS WILL BE SUPPLIED ON OUR PRODUCTION UNITS
 - 19.) THIS HAS NOT PROVED TOO SERIOUS A
 PROBLEM WITH A LITTLE EXPERIENCE
 IN REMOVAL AND INSTALLATION
 - 18.) INFLIGHT ENECTION TEST RIGS (CILL HAVE A NEWLY TAMORED PACK.
 - 19.) MR. SHEPPARDSON PER TELECON OF 9/28/64

 Does NOT FEEL THIS IS A PROBLEM SINCE

 RECOVERY WAS ACHIEVED.
 - 26.) HARNESS HAS BEEN STATICALLY POLLED Approved For Release 2002/10/21: CIA-RDP75800285H000400020014-7C

Approved Factories 2002/10/21	: CIA-RDP75B00265R000400020014-1
ACTUATORS: 1.) PAN WAS AND ANY FURTHER	(Du Besupplied FOR TESTING REQUIRED BY CAN
2.) WILL INVESTIG POSSIBLE ON	PRODUCTION RIGS
3.) AGREED (PS	()
STATINTL REF	

- 1.) A.) PAN WILL BE SUPPLIED.
 - B) (Psc Acriew)

. . . .

- C) (PSC AcTION)
- D) I DONOT FEEL THAT IS A
 PROBLEM. DETENT (ULL BE
 RELOCATED 10° PER AGREEMENT
 (ULTH N. BICE PSC.
- 2. A.) RESERVE JUDGEMENT UNTIL COMPLETION OF LIVE JUMPS - SO FAR NO PRODUCTION ON LIVES.
 - B.) So FAR NO PROBLEM ON LIVE JUMPS
 - C.) WILL BE INCORPORATION ON PROD RIGS

Approved For Release	2002/10/21 :	CIA-RDP75B000057R000400020014-1
----------------------	--------------	---------------------------------

3. A.) C&J AcTION	
B.) Of S Horion	
C.) RESERVE SUDGEMENT UNTIL EJECTION TESTS COMPLETE	ប
D. WILL DOE FURTHER INVESTIGATION DOWN BEING CONDUCTED TO IMPROVE EVEN MORE	T 7 O K
E. C& J AcTION	
F. WILL DUESTIGATE	
4. Refer To	TINTL
PSC ACTUATOR FAILURE REPORT	
I DO NOT AGREE WILL CONCLUSION AS BTATED. FURTHER LORITTEN REPORT WILL BE SUBMITTED BY J.KS STATE	′_ TINTL
7	